



# Digital Thermometer & Hygrometer

## Features

1. Display shows temperature, humidity, and max/min values.
2. Temperature can be displayed in Fahrenheit and Celsius.
3. Maximum and minimum value can be easily reset.

## Specifications

1. Temperature measuring range: -10 ~50° C (14-122° F)
2. Humidity measuring range: 10% ~99%RH
3. Power supply: Two AAA batteries (not included)

## Operation

Two buttons are located on the back of the hygrometer to adjust the display settings.

1. **°F/°C:** Press to toggle between displaying temperatures in Fahrenheit or Celsius.
2. **CLEAR:** Press to reset the min and max temperature and humidity readings.

## Proper Care

1. Keep product clean. A build up of dust could effect the accuracy of the thermometer and hygrometer.
2. Do not drop as it may damage the sensitive electronics.
3. For indoor use only. Keep away from water.
4. Replace batteries when the display begins to dim.

Customer Service: PO Box 1848, Grand Island, NE 68802-1848  
1-877-214-4470 | Email: [info@snapsafe.com](mailto:info@snapsafe.com)