


STUCK CASE REMOVER

The Hornady Stuck Case Remover is designed to remove stuck cases from the size die body.

1. Back the deprime spindle out of the die as far as it will go and remove the die from the press.
2. Drill a hole through the primer pocket with the #7 drill provided.
3. Tap the hole with 1/4" x 20 Tap provided.
4. Place the Stuck Case Remover Body over the end of the Die; cupped sided facing the bottom of the Die.
5. With the washer on the Socket Head Cap Screw (SHCS), insert it thru the Case Stuck Remover Body, and screw it into the threaded case. Continue tightening the Cap Screw against the Body until the stuck case is removed from the die.



PARTS LIST

390128..... Washer

392066..... 1/4" x 20 Tap

392067..... #7 Drill

392068..... Body

398388..... 1/4" x 20 x 1 1/2" SHCS



Hornady
Accurate. Deadly. Dependable.

P.O. Box 1848, Grand Island, NE 68802-1848
308-382-1390 • 800-338-3220 • Fax: 308-382-5761 • hornady.com/contact