

POWDER THROUGH EXPANDERS

Before you begin using these expanders, please follow these quick instructions.

- Clean and degrease
- Insert the PTX Expander, small nose pointing down, into the Powder Adapter
(See Part 21 in the CAPD Bill of Materials and Exploded View in the Powder Measure and Case Activated Powder Drop Instruction Manual).
- Re-install the Powder Measure.
(Refer to Final Powder Measure Assembly section in the Powder Measure and Case Activated Powder Drop Instruction Manual).
- Case Activated Powder Drop Adjustments
(Refer to this section in the Powder Measure and Case Activated Powder Drop Instruction Manual).

The PTX Expander will expand and flare your case and drop powder at the same time. PTX expanders are engineered to expand your case mouth to the proper diameter when the powder measure is properly adjusted.



Hornady
Accurate. Deadly. Dependable.

P.O. Box 1848, Grand Island, NE 68802-1848
hornady.com/contact